#### **ECE 486: Control Systems**

Lecture 16C: Phase Margin

# Key Takeaways

This lecture discusses another safety factor called the phase margin to account for model uncertainty and time delays.

- The phase margin is the amount of allowable variation in the phase of the plant before the closed-loop becomes unstable.
- As a rule of thumb, the closed-loop should remain stable for phase variations in the range ±45°.


It is shown that a phase variation  $\theta_0 > 0$  causes a closed-loop pole at  $s = j\omega_0$  if and only if  $e^{-j\theta_0}L(j\omega_0) = -1$ .

This can be used to determine phase margins from a Bode plot of the loop transfer function *L(s)*.

# **Phase Margin**

The phase margin is another "safety factors" developed to account for the mismatch between the design model and the dynamics of the real system.

- Design model G(s) might differ from real dynamics by a phase *θ>0*.
   Phase variations can also occur due to time delays.
- Assume the closed-loop is stable with the nominal model ( $\theta=0$ ).
- The closed-loop may become unstable as  $\theta$  is varied away from  $\theta=0$ .
- The phase margin measures the variation before instability occurs.




## **Phase Margin**

**Definition:** The **phase margin** is an upper limit  $\overline{\theta} > 0$  such that:

- 1. the closed-loop is stable for all phase variations  $\theta$  in the range  $-\overline{\theta} < \theta < \overline{\theta}$ , and
- 2. the closed-loop is unstable for  $\theta = \overline{\theta}$  (if  $\overline{\theta} < \infty$ )

As a rule of thumb, the closed-loop should remain stable for phase variations of at least ±45°.



## **Critical Phases**

The closed-loop poles move continuously in the complex plane as the phase  $\theta$  is varied away from 0.

Critical phases are values of  $\theta$  for which the closed-loop poles are on the imaginary axis. These phases mark the transition between stable (LHP) and unstable (RHP).

- A critical phase  $\theta_0$  causes a closed-loop pole at  $s = \pm j\omega_0$ .
- A critical phase  $\theta_0$  causes  $1 + e^{-j\theta_0}L(j\omega_0) = 0$ .

A critical phase  $\theta_0 > 0$  cause a closed-loop pole at  $s = \pm j\omega_0$  if and only if  $e^{-j\theta_0}L(j\omega_0) = -1$ .

## **Connection to Bode Plots**

A critical phase  $\theta_0 > 0$  cause a closed-loop pole at  $s = \pm j\omega_0$  if and only if  $e^{-j\theta_0}L(j\omega_0) = -1$ . Identify on a Bode plot by:

- **1**. Find frequencies where  $|L(\omega_0)| = 1 = 0dB$ . These are called *gain crossing or phase margin frequencies.*
- 2. The critical phase satisfies  $-\theta_0 + \angle L(j\omega_0) = -180^o$ . Thus the critical phases are  $\theta_0 = \angle L(j\omega_0) + 180^o$ .
- **3.** This critical phase causes the closed-loop poles at  $s = \pm j\omega_0$ . The phase margin  $\overline{\theta}$  corresponds to the smallest critical phase (in magnitude).

The Matlab function allmargin computes all critical phases and corresponding gain crossing frequencies.

#### Example

Consider the feedback system with:


$$G(s) = \frac{1}{s^3 + 2s^2 + 3s + 1}$$
 and  $K(s) = 2$ .  
 $\Rightarrow L(s) = G(s)K(s) = \frac{2}{s^3 + 2s^2 + 3s + 1}$ .

The nominal sensitivity is:

$$S(s) = \frac{1}{1+L(s)} = \frac{s^3 + 2s^2 + 3s + 1}{s^3 + 2s^2 + 3s + 3}.$$

The poles of S(s) are:  $s_{1,2} = -0.30 \pm 1.44j$  and  $s_3 = -1.39$ .

These are all in the LHP so the nominal closed-loop is stable.




# Example

Consider the feedback system with:

 $G(s) = \frac{1}{s^3 + 2s^2 + 3s + 1}$  and K(s) = 2.  $\Rightarrow L(s) = G(s)K(s) = \frac{2}{s^3 + 2s^2 + 3s + 1}$ .

- **1**. There is one phase margin frequency:  $\omega_0 = 0.86 \frac{rad}{sec}$ .
- 2. The loop phase is  $\angle L(j\omega_0) = -103.7^o$ . The critical phase is  $\theta_0 = \angle L(j\omega_0) + 180^o = 76.3^o$ .
- 3. The phase  $\theta_0$  causes a closed- (g) loop pole at  $s = \pm j\omega_0$ .

The phase margin is  $\overline{\theta} = 76.3^{\circ}$ .



## Example

Revisit the feedback system with:

 $G(s) = \frac{1}{s^3 + 2s^2 + 3s + 1}$  and K(s) = 2.  $\Rightarrow L(s) = G(s)K(s) = \frac{2}{s^3 + 2s^2 + 3s + 1}$ .

```
>> L = tf(2, [1 \ 2 \ 3 \ 1]);
>> AM = allmargin(L);
>> theta0 = AM.PhaseMargin
76.2741
>> w0 = AM.PMFrequency
0.8586
\% Verify that theta0 causes a closed-loop pole at s=+jw0
>> theta0rad = theta0*pi/180; % Convert from degs to rads
>> S0 = feedback(1, exp(-1j*theta0rad)*L);
>> pole(S0)
-0.6568 - 1.6803i
-1.3432 + 0.8216i
0.0000 + 0.8586i
```